

Appendix B

Fiscal Year 2002 Operable Unit 4-13 Operations and Maintenance Inspection Photos

Appendix B

Fiscal Year 2002 Operable Unit 4-13 Operations and Maintenance Inspection Photos




Figure B-1. CERCLA sign identifying locations of CFA-01, CFA-02 and CFA-03 (PD020605-35).




Figure B-2. Institutional control sign for CFA-01 Landfill I (PD020605-15).



Figure B-3. View of CFA-01 Landfill I looking to the northwest (PD020605-16).



Figure B-4. Rabbit brush (typical) at the CFA-01 Landfill I (PD020605-19).



Figure B-5. Erosion rill at CFA-01 Landfill I (PD020605-20).